			I					
ID#	Туре	Class	Protective Earth Resistance	Insulation Resistance	Leakage Current	Cord	Result	Notes
0001	Lighting	Class I	0.05Ω	>19.99MΩ	<.010mA		PASS	
0002	Lighting	Class I	0.06Ω	>19.99MΩ	<.010mA		PASS	
0003	Lighting	Class I	0.08Ω	>19.99MΩ	<.010mA		PASS	
0004	Lighting	Class I	0.07Ω	>19.99MΩ	<.010mA		PASS	
0005	Lighting	Class I	0.03Ω	>19.99MΩ	0.18mA		PASS	
0006	Lighting	ClassI	0.04Ω	>19.99MΩ	0.16mA		PASS	
0007	Amplifier	Class I	0.04Ω	>19.99MΩ	<.010mA	Y	PASS	
8000	Mixers	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0009	Cable	Cable	0.05Ω	>19.99MΩ		GOOD	PASS	5A Fuse
0010	Mixers	Class II	Double Insulated	>19.99MΩ	<.010mA	Υ	PASS	
0011	Mixers	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0012	Laptop	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0013	Laptop	Class II	Double Insulated	>19.99MΩ	<.010mA	Υ	PASS	3A Fuse
0014								
0015	Lighting	Class II	No Continuity	>19.99MΩ	<.010mA	Υ	PASS	Plastic Body 3A Fuse
0016	Lighting	Class II	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body 3A Fuse
0017	Lighting	Class I	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body 3A Fuse
0018	Lighting	Class I	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body 3A Fuse
0019	Lighting	Class I	0.11Ω	>19.99MΩ	0.16mA	Υ	PASS	3A Fuse
0020	Lighting	Class I	0.14Ω	>19.99MΩ	0.15mA	Y	PASS	3A Fuse
0021	Microphones	Class II	Double Insulated	>19.99MΩ	<.010mA	Υ	PASS	
0022	Lighting	Class II	Double Insulated	>19.99MΩ	<.010mA		PASS	3A Fuse
0023	Speakers	Class I	0.05Ω	>19.99MΩ	0.92mA	Y	PASS	IT Equipment < 3.0mA
0024	F-311010		2.302					-1F2114 0.0114.
0025	Speakers	Class I	0.06Ω	>19.99MΩ	0.93mA	Υ	PASS	IT Equipment < 3.0mA
0026	Cables	Cable	0.02Ω	>19.99MΩ	0.0011111	GOOD	PASS	13A Fuse
0027	Speakers	Class I	0.05Ω	>19.99MΩ	0.78mA	GOOD	PASS	IT Equipment < 3.0mA
0027	Speakers	Class I	0.03Ω	>19.99MΩ	<0.10mA	Y	PASS	IT Equipment < 3.0mA
	·							
0029	Speakers	Class I	0.05Ω	>19.99MΩ	<.010mA	Y	PASS	IT Equipment < 3.0mA
0030	Cables	Cable	0.07Ω	>19.99MΩ		GOOD	PASS	5A Fuse
0031	Cables	Cable	0.09Ω	>19.99MΩ		GOOD	PASS	5A Fuse
0032	Effects	Class I	0.10Ω	>19.99MΩ	<.010mA	Y	PASS	
0033	Cables	Cable	0.05Ω	>19.99MΩ		GOOD	PASS	5A Fuse
0034	Lighting	Class I	0.08Ω	>19.99MΩ	<0.10mA	Y	PASS	
0035	Cables	Cable	0.04Ω	>19.99MΩ	<.010mA	Y	PASS	3A Fuse
0036	Other	Class II	Double Insulated	>19.99MΩ	<0.10mA		PASS	13A Fuse
0037	Other	Class II	Double Insulated	>19.99MΩ	<.010mA			3A Fuse
0038	Speakers	Class I	0.05Ω	>19.99MΩ	0.84mA	Y	PASS	IT Equipment < 3.0mA
0039	Speakers	Class I	0.06Ω		0.78mA	Y	PASS	IT Equipment < 3.0mA
0040	Cables	Cable	0.08Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0041	Cables	Cable	0.02Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0042								
0043	Cables	Cable	0.06Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0044	Cables	Cable	0.12Ω	0.31Ω		GOOD	PASS	Riso Fail Tested at 500v 13A fuse
0045	Cables	Cable	0.07Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0046	Cables	Cable	0.05Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0047	Cables	Cable	0.05Ω	>19.99MΩ		GOOD	PASS	3A Fuse
0048	Mixers	Mixer	Double Insulated	>19.99MΩ	<.010mA		PASS	3A Fuse
0049	Cables	Cable	0.04Ω	>19.99MΩ		GOOD	PASS	IEC TO IEC – BS1363A PLUG
0050	Cable	Cable	0.04Ω	0.30Ω		GOOD	PASS	Riso Fail Tested at 500v 13A fuse
0051	Cables	Cable	0.07Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0052	Cables	Cable	0.03Ω	>19.99MΩ		GOOD	PASS	IEC TO IEC
0053								-
0054	Cables	Cable	0.06Ω	>19.99MΩ		GOOD	PASS	5A Fuse
0055	Cables	Cable	0.02Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0056	Cables	Cable	0.06Ω	>19.99MΩ		GOOD	PASS	5A Fuse
0057	Cables	Cable	0.14Ω	>19.99MΩ		GOOD	PASS	13A Fuse
				>19.99MΩ >19.99MΩ		GOOD		
0058	Cables	Cable	0.10Ω				PASS	13A Fuse
0059	Cables	Cable	0.11Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0060	Cables	Cable	0.12Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0061	Cables	Cable	0.09Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0062	Cables	Cable	0.09Ω	>19.99MΩ	0.15	GOOD	PASS	13A Fuse
0063	Lighting	Class I	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body, No Exposed Metal. 3A Fuse

Lighting Class No Community >19 0.0000							1		I
	0064	Lighting	Class I	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body, No Exposed Metal. 3A Fuse
Lighting Class No Continually >19.98600 <0.10mA PASS Pleatic Roy, No Expected Model	0065	Lighting	Class I	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body, No Exposed Metal. 3A Fuse
	0066	Lighting	Class I	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body, No Exposed Metal. 3A Fuse
Lighting	0067	Lighting	Class I	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body, No Exposed Metal. 3A Fuse
Lighting	0068	Lighting	Class I	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body, No Exposed Metal. 3A Fuse
Lighting	0069	Lighting	Class I	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body, No Exposed Metal. 3A Fuse
Lighting	0070	Lighting	Class I	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body, No Exposed Metal. 3A Fuse
1071 1072 1073 1074	0071	Lighting	Class I	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body, No Exposed Metal. 3A Fuse
1077	0072	Lighting	Class I	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body, No Exposed Metal. 3A Fuse
	0073								
	0074								
1,000 1,00									
Cables		Liahtina	Class I	0.04Ω	>19.99MΩ	0.18mA		PASS	
Cables Cable Ca									
1,000 1,0						3.0 101117	GOOD		5A Fuse
Commonstrate Comm						< 0.10m A			JAT use
COP Deliyer Class Double Insulated >19.99MΩ <010mA PASS 3A Fuse							<u> </u>		3V Erico
CODE Depart Class II No Continuity No Continuity PASS Plastic Body 3 Fuse PASS Plastic Body 3 Fuse PASS Class II No Continuity PASS Plastic Body 3 Fuse P									
College									
Deuble Insulated >19.99MΩ <.010mA PASS 18ν AC PSU		-			>19.99MΩ	<.UTUMA			
Color Col				,	. 10.00110	. 040 . 4			-
Cable Cab									
Cables Cables Cable 0.01Ω >19.99MΩ GOOD PASS 13A Fuse		-							
Cables Cables Cable 0.02Ω >19.99MΩ GOOD PASS 13A Fuse			Class II			<.010mA			
Cables Cable Cable 0.05Ω >19.99MΩ GOOD PASS 13A Fuse	0087	Cables	Cable		>19.99MΩ				13A Fuse
Cables Cable Cable Cable 0.04Ω >19.99MΩ GOOD PASS 13A Fuse 13A Fuse 0.092 Cables Cable 0.09Ω >19.99MΩ GOOD PASS 13A Fuse 0.092 Cables Cable 0.04Ω >19.99MΩ GOOD PASS 13A Fuse 0.093 Cables Cable 0.04Ω >19.99MΩ Cables Cable 0.04Ω >19.99MΩ Cables Cable 0.04Ω >19.99MΩ Cables Cable 0.03Ω >19.99MΩ Cables Cable 0.03Ω >19.99MΩ Cables Cable 0.03Ω >19.99MΩ Cables Cable 0.03Ω >19.99MΩ Cables Cable 0.04Ω >19.99MΩ Cables Cable 0.04Ω >19.99MΩ Cables Cable Cable 0.04Ω >19.99MΩ Cables Cable Cable 0.04Ω Cables Cable 0.05Ω Cables	0088	Cables	Cable	0.02Ω	>19.99MΩ				13A Fuse
Cables Cable Cable 0.09Ω >19.99MΩ GOOD PASS 13A Fuse	0089	Cables	Cable	0.05Ω	>19.99MΩ		GOOD	PASS	13A Fuse
Cables Cable Cable O.04Ω >19.99MΩ GOOD PASS 13A Fuse	0090	Cables	Cable	0.04Ω	>19.99MΩ		GOOD	PASS	13A Fuse
Cables Cable Cable 0.04Ω >19.99MΩ <.010mA GOOD PASS IEC TO IEC	0091	Cables	Cable	0.09Ω	>19.99MΩ		GOOD	PASS	13A Fuse
Cables Cable Cable 0.03Ω >19.99MΩ <.010mA GOOD PASS IECTO IEC	0092	Cables	Cable	0.04Ω	>19.99MΩ		GOOD	PASS	13A Fuse
Cables Cable Ca	0093	Cables	Cable	0.04Ω	>19.99MΩ	<.010mA	GOOD	PASS	IEC TO IEC
Cables Cable Cable O.04Ω >19.99MΩ <.010mA GOOD PASS IEC TO IEC	0094	Cables	Cable	0.03Ω	>19.99MΩ	<.010mA	GOOD	PASS	IEC TO IEC
Cables Cable Ca	0095	Cables	Cable	0.03Ω	>19.99MΩ	<.010mA	GOOD	PASS	IEC TO IEC
Cables Cable Ca	0096	Cables	Cable	0.04Ω	>19.99MΩ	<.010mA	GOOD	PASS	IEC TO IEC
Cables Cable Cable 0.02Ω >19.99MΩ Y PASS 13A Fuse	0097	Cables	Cable	0.04Ω	>19.99MΩ		GOOD	PASS	10A Fuse
Cables Cable Cable 0.06Ω >19.99MΩ GOOD PASS 5A Fuse	0098	Cables	Cable	0.04Ω	>19.99MΩ		GOOD	PASS	5A Fuse
O102 Cables Cable O.19MΩ >19.99MΩ GOOD PASS 10A Fuse	0099	Cables	Cable	0.02Ω	>19.99MΩ		Y	PASS	13A Fuse
Cables Cable Ca	0100	Cables	Cable	0.06Ω	>19.99MΩ		GOOD	PASS	5A Fuse
Cables Cable Ca	0101								
Cables Cable Cable 0.07Ω >19.99MΩ GOOD PASS 13A Fuse 105 Cable Cable 0.01Ω >19.99MΩ GOOD PASS 3A Fuse 106 Cables Cable 0.05Ω >19.99MΩ GOOD PASS 5A Fuse 107 Cables Cable 0.07Ω >19.99MΩ GOOD PASS 5A Fuse 108 Cables Cable 0.12Ω >19.99MΩ GOOD PASS 5A Fuse 108 Cables Cable 0.18Ω >19.99MΩ GOOD PASS 5A Fuse 109 Cables Cable 0.18Ω >19.99MΩ GOOD PASS 13A Fuse 1010 Amplifier Class 0.07Ω >19.99MΩ 0.24mA Y PASS 13A Fuse 13A Fuse 1011 Microphones Class Double Insulated >19.99MΩ C.010mA Y PASS 13A Fuse 1011 Cables Cable 0.04Ω >19.99MΩ 0.86mA Y PASS IT Equipment < 3.0mA 1015 Speakers Class 0.07Ω >19.99MΩ 0.86mA Y PASS IT Equipment < 3.0mA 1015 Speakers Cable 0.01Ω >19.99MΩ 0.82mA Y PASS IT Equipment < 3.0mA 1016 Cables Cable 0.01Ω >19.99MΩ 0.82mA Y PASS IT Equipment < 3.0mA 1016 Cables Cable 0.01Ω >19.99MΩ 0.010mA Y PASS IT Equipment < 3.0mA 1016 Cables Cable 0.01Ω >19.99MΩ 0.010mA Y PASS IT Equipment < 3.0mA 1016 Cables Cable 0.01Ω >19.99MΩ 0.010mA Y PASS IT Equipment < 3.0mA 1017 Lighting Class 0.13Ω >19.99MΩ 0.010mA Y PASS 5A Fuse 1017 Lighting Class 0.13Ω >19.99MΩ 0.010mA Y PASS 5A Fuse 1018 Monitor Class 0.010 Noble Insulated >19.99MΩ 0.010mA Y PASS 5A Fuse 1019 Cables Cable 0.04Ω >19.99MΩ 0.010mA Y PASS 13A Fuse 1012 Cables Cable 0.04Ω >19.99MΩ 0.010mA Y PASS 13A Fuse 1012 Cables Cable 0.04Ω >19.99MΩ 0.010mA Y PASS 13A Fuse 1012 Cables Cable 0.04Ω >19.99MΩ 0.010mA Y PASS 13A Fuse 1012 Cables Cable 0.04Ω >19.99MΩ 0.010mA Y PASS 13A Fuse 1012 Cables Cable 0.04Ω >19.99MΩ 0.010mA Y PASS 13A Fuse 1012 Cables Cable 0.04Ω >19.99MΩ 0.010mA Y PASS 13A Fuse 1012 Cables Cabl	0102	Cables	Cable	0.19ΜΩ	>19.99MΩ		GOOD	PASS	10A Fuse
0105 Cable Cable 0.01Ω >19.99MΩ GOOD PASS 3A Fuse 0106 Cables Cable 0.05Ω >19.99MΩ GOOD PASS 5A Fuse 0107 Cables Cable 0.07Ω >19.99MΩ GOOD PASS 5A Fuse 0108 Cables Cable 0.12Ω >19.99MΩ GOOD PASS 5A Fuse 0109 Cables Cable 0.18Ω >19.99MΩ GOOD PASS 13A Fuse 0110 Amplifier Class I 0.07Ω >19.99MΩ 0.24mA Y PASS 13A Fuse 0111 Microphones Class II Double Insulated >19.99MΩ <010mA Y PASS 10.5V 0.25A PSU 0113 Cables Cable 0.04Ω >19.99MΩ <0.00mA Y PASS IT Equipment < 3.0mA 0114 Speakers Class I 0.07Ω >19.99MΩ 0.82mA Y PASS IT Equipment < 3.0mA 0115 <t< td=""><th>0103</th><td>Cables</td><td>Cable</td><td>0.20ΜΩ</td><td>>19.99MΩ</td><td></td><td>GOOD</td><td>PASS</td><td>10A Fuse</td></t<>	0103	Cables	Cable	0.20ΜΩ	>19.99MΩ		GOOD	PASS	10A Fuse
Cables Cable Ca	0104	Cables	Cable	0.07Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0107 Cables Cable 0.07Ω >19.99ΜΩ GOOD PASS 5A Fuse 0108 Cables Cable 0.12Ω >19.99ΜΩ GOOD PASS 5A Fuse 0109 Cables Cable 0.18Ω >19.99ΜΩ GOOD PASS 13A Fuse 0110 Amplifier Class I 0.07Ω >19.99ΜΩ <.010mA Y PASS 13A Fuse 0111 Microphones Class II Double Insulated >19.99MΩ <.010mA Y PASS 10.5V 0.25A PSU 0113 Cables Cable 0.04Ω >19.99MΩ <.010mA Y PASS 17 Equipment < 3.0mA 0114 Speakers Class I 0.08Ω >19.99MΩ 0.86mA Y PASS IT Equipment < 3.0mA 0115 Speakers Class I 0.07Ω >19.99MΩ 0.82mA Y PASS IT Equipment < 3.0mA 0116 Cables Cable 0.01Ω >19.99MΩ 0.82mA Y PASS IT	0105	Cable	Cable	0.01Ω	>19.99MΩ		GOOD	PASS	3A Fuse
0108 Cables Cable 0.12Ω >19.99MΩ GOOD PASS 5A Fuse 0109 Cables Cable 0.18Ω >19.99MΩ GOOD PASS 13A Fuse 0110 Amplifier Class I 0.07Ω >19.99MΩ 0.24mA Y PASS 13A Fuse 0111 Microphones Class II Double Insulated >19.99MΩ <.010mA Y PASS 10.5V 0.25A PSU 0113 Cables Cable 0.04Ω >19.99MΩ <.010mA Y PASS 13A Fuse 0114 Speakers Class 1 0.08Ω >19.99MΩ 0.86mA Y PASS IT Equipment < 3.0mA 0115 Speakers Class 1 0.07Ω >19.99MΩ 0.82mA Y PASS IT Equipment < 3.0mA 0116 Cables Cable 0.01Ω >19.99MΩ <.010mA Y PASS 13A Fuse 0117 Lighting Class I Double Insulated >19.99MΩ <.010mA Y <t< td=""><th>0106</th><td>Cables</td><td>Cable</td><td>0.05Ω</td><td>>19.99MΩ</td><td></td><td>GOOD</td><td>PASS</td><td>5A Fuse</td></t<>	0106	Cables	Cable	0.05Ω	>19.99MΩ		GOOD	PASS	5A Fuse
O109 Cables Cable 0.18Ω >19.99ΜΩ GOOD PASS 13A Fuse 0110 Amplifier Class I 0.07Ω >19.99ΜΩ 0.24mA Y PASS 13A Fuse 0111 Microphones Class II Double Insulated >19.99MΩ <.010mA Y PASS 10.5V 0.25A PSU 0113 Cables Cable 0.04Ω >19.99MΩ GOOD PASS 17 Equipment < 3.0mA 0114 Speakers Class 1 0.08Ω >19.99MΩ 0.82mA Y PASS IT Equipment < 3.0mA 0115 Speakers Class 1 0.07Ω >19.99MΩ 0.82mA Y PASS IT Equipment < 3.0mA 0116 Cables Cable 0.01Ω >19.99MΩ 0.82mA Y PASS IT Equipment < 3.0mA 0116 Cables Cable 0.01Ω >19.99MΩ 0.010mA Y PASS 13A Fuse 0117 Lighting Class I Double Insulated >19.99MΩ <0.010mA	0107	Cables	Cable	0.07Ω	>19.99MΩ		GOOD	PASS	5A Fuse
O110 Amplifier Class I 0.07Ω >19.99ΜΩ 0.24mA Y PASS 13A Fuse O111 Microphones Class II Double Insulated >19.99ΜΩ <.010mA	0108	Cables	Cable	0.12Ω	>19.99MΩ		GOOD	PASS	5A Fuse
0111 Double Insulated >19.99ΜΩ <.010mA	0109	Cables	Cable	0.18Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0112 Microphones Class II Double Insulated >19.99ΜΩ <.010mA	0110	Amplifier	Class I	0.07Ω	>19.99MΩ	0.24mA	Y	PASS	13A Fuse
0112 Microphones Class II Double Insulated >19.99ΜΩ <.010mA		·							
0113 Cables Cable 0.04Ω >19.99ΜΩ GOOD PASS 13A Fuse 0114 Speakers Class 1 0.08Ω >19.99ΜΩ 0.86mA Y PASS IT Equipment < 3.0mA 0115 Speakers Class 1 0.07Ω >19.99MΩ 0.82mA Y PASS IT Equipment < 3.0mA 0116 Cables Cable 0.01Ω >19.99MΩ GOOD PASS 13A Fuse 0117 Lighting Class I 0.13Ω >19.99MΩ <.010mA Y PASS 5A Fuse 0118 Monitor Class II Double Insulated >19.99MΩ <0.10mA Y PASS 13A Fuse 0119 Other Class II Double Insulated >19.99MΩ <0.010mA Y PASS 5A Fuse 0120 Cables Cable 0.04Ω >19.99MΩ <0.010mA Y PASS 0121 Effects Class I Double Insulated >19.99MΩ <0.010mA Y PASS		Microphones	Class II	Double Insulated	>19.99MΩ	<.010mA	Υ	PASS	10.5V 0.25A PSU
0114 Speakers Class 1 0.08Ω >19.99ΜΩ 0.86mA Y PASS IT Equipment < 3.0mA									
0115SpeakersClass 1 0.07Ω >19.99MΩ 0.82mA YPASSIT Equipment < 3.0mA						0.86mA			IT Equipment < 3.0mA
0116CablesCable 0.01Ω >19.99MΩGOODPASS13A Fuse0117LightingClass I 0.13Ω >19.99MΩ<.010mAYPASS5A Fuse0118MonitorClass IIDouble Insulated>19.99MΩ<0.10mAYPASS13A Fuse0119OtherClass IIDouble Insulated>19.99MΩ<.010mAYPASS5A Fuse0120CablesCable 0.04Ω >19.99MΩGOODPASS13A Fuse0121EffectsClass IIDouble Insulated>19.99MΩ<.010mAYPASS0122LightingClass I 0.07Ω >19.99MΩ<.010mAYPASS									· ·
0117 Lighting Class I 0.13Ω >19.99ΜΩ <.010mA						0.020.000			· ·
0118 Monitor Class II Double Insulated >19.99ΜΩ <0.10mA						< 010mA			
0119 Other ClassII Double Insulated >19.99ΜΩ <.010mA									
0120 Cables Cable 0.04Ω >19.99ΜΩ GOOD PASS 13A Fuse 0121 Effects Class II Double Insulated >19.99ΜΩ <.010mA									
0121 Effects Class II Double Insulated >19.99ΜΩ <.010mA									
0122 Lighting Class I 0.07Ω >19.99ΜΩ <.010mA						< 010mA			IO/ CLUGG
								1 700	3 A Fugg
	0122		Class I	0.07Ω	>19.99MΩ >19.99MΩ	<.010mA	Y	PASS	3A Fuse
		Lighting				>.U IUIIIA			
0124 Cables Cable 0.19Ω >19.99ΜΩ GOOD PASS 10A Fuse 0435 Cables Cables 0.05Ω >40.00MΩ COOD PASS 43A Fuse									
0125 Cables Cable 0.05Ω >19.99ΜΩ GOOD PASS 13A Fuse									
									Riso Fail Tested at 500v 13A fuse
0127 Cables Cable 0.04Ω >19.99ΜΩ GOOD PASS 13A Fuse	U127	Cables	Caple	υ.υ4Ω	>19.99MΩ		GOOD	PASS	13A Fuse

0420	Cablas	Cabla			7	Υ	PASS	Riso Fail Tested at 500v 13A fuse
0128 0129	Cables Cables	Cable Cable	0.04Ω	0.31Ω		GOOD	PASS	Riso Fail Tested at 500v 13A fuse
0130	Cables	Cable	0.04Ω	0.30Ω		Y	PASS	Riso Fail Tested at 500v 13A fuse
0131	Cables	Cable	0.05Ω	0.30Ω		GOOD	PASS	Riso Fail Tested at 500v 13A fuse
0131	Cables	Cable	0.03Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0132	Cables	Cable	0.20Ω	>19.99MΩ		GOOD	PASS	0.25Ω Rpe Limit for 1.5mm CSA 13A
0134	Cables	Cable	0.2012	> 13.33WIZ2		Y	PASS	13A Fuse
0135	Cables	Cable	0.07Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0136	Lighting	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	3A Fuse
0137	Lighting	Class II	Double Insulated	> 13.33WIZ2	V.010111A	'	1 700	JAT use
0138	Speakers	Class I	0.02Ω	>19.99MΩ	0.82mA	Y	PASS	IT Equipment < 35mA
0139	Cables	Cable	0.02Ω	>19.99MΩ	0.02IIIA	GOOD	PASS	13A Fuse
0139	Speakers	Class I	0.05Ω	>19.99MΩ	0.95mA	GOOD	PASS	IT Equipment < 35mA
0141	Cables	Cable	0.02Ω	>19.99MΩ	0.95IIIA	GOOD	PASS	13A Fuse
0141	Speakers	Class I	0.02Ω	>19.99MΩ	0.81mA	Y	PASS	IT Equipment < 35mA
0142	Speakers	Class I	0.122	>13.33IVI22	0.0 IIIIA	<u> </u>	FAGG	11 Equipment < 55mA
0144	Cables	Cable	0.4Ω	>19.99MΩ		GOOD	PASS	(0.49mA Limit) 13a Fuse
0145	Cables	Cable	V.4-12	> 13.33WIZ2		GOOD	1 700	(0.4911A Ellilli) 13a i use
0145	Other	Other	0.01Ω	>19.99MΩ		GOOD	PASS	RCD Protector
0147	Cables	Cable	0.06Ω	>19.99MΩ		GOOD	PASS	3A Fuse
0148	Cables	Cable	0.07Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0149	Cables	Cable	0.07Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0150	Cables	Cable	0.04Ω	>19.99MΩ		GOOD	PASS	5A Fuse
0151	Cables	Cable	0.04Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0152	Other	Class II	Double Insulated	>19.99MΩ	<.010mA	0002	PASS	12v 1A PSU
0153	Cable	Cable	0.08Ω	>19.99MΩ	2.0101117	GOOD	PASS	13A Fuse
0154	Lighting	Class I	0.06Ω	>19.99MΩ	0.11mA	Y	PASS	1971. 433
0155		0.000.	0.001	10.0022	0		. ,	
0156	Other	Other	0.01Ω	>19.99MΩ		GOOD	PASS	13A Fused
0157	Microphones	ClassII	Double Insulated	>19.99MΩ	<.010mA	GOOD	PASS	12V 0.4A PSU 3A Fuse
0158	Cable	Cable	0.1Ω	>19.99ΜΩ		GOOD	PASS	13A Fuse
0159	Cable	Cable	0.05Ω	>19.99ΜΩ		GOOD	PASS	13A Fuse
0160	Lights	Class II	Double Insulated	>19.99ΜΩ	<.010mA		PASS	31V PSU
0161	Other	Heater	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	13A Fuse
0162	Cables	Cable				Y	PASS	13A Fuse
0163	Light	Class I	0.07Ω	>19.99MΩ	<.010mA		PASS	10111 22
0164	Light	Class I	0.07Ω	>19.99MΩ	<.010mA		PASS	
0165	Light	Class I	0.05Ω	>19.99MΩ	<.010mA		PASS	
0166	Light	Class I	0.05Ω	>19.99MΩ	<.010mA		PASS	
0167								
0168								
0169	Cables	Cable	0.01Ω	>19.99MΩ		Y	PASS	3A Fuse
0170								
0171	Cables	Cable	0.08Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0172	Cables	Cable	0.08Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0173	Cables	Cable	0.08Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0174	Cables	Cable	0.08Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0175								
0176								
0177	Cables	Cable	0.05Ω	>19.99MΩ		GOOD	PASS	5A Fuse
0178								
0179	Cables	Cable	0.02Ω	>19.99MΩ		GOOD	PASS	13A Fuse
0180	Cables	Cable	0.08Ω	0.32mA		GOOD	PASS	Riso Fail Tested at 500v 13A fuse
0181	Cables	Cable	0.08Ω	0.31mA		GOOD	PASS	Riso Fail Tested at 500v 13A fuse
0182	Light	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0183	Light	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0184	Light	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0185	Light	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0186	Light	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0187	Light	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0188	Light	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0189	Light	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0190	Light	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0191	Light	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	

0192	Light	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0193	Light	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0194	Speakers	Class I	0.05Ω	>19.99MΩ	0.89mA	Y	PASS	IT Equipment < 35mA
0195	Speakers	Class I	0.02Ω	>19.99MΩ	0.87mA	Y	PASS	IT Equipment < 35mA
0196	Cable	Cable	0.03Ω	>19.99MΩ		GOOD	PASS	3A Fuse
0197	Cable	Cable	0.05Ω	>19.99MΩ		GOOD	PASS	3A Fuse
0198	Light	Class II	Double Insulated	>19.99MΩ	<.010mA	Y		3A Fuse
0199	Lighting	Class I	No Continuity	>19.99MΩ	<.010mA		PASS	Plastic Body, No Exposed Metal. 3A Fuse
0200	Laptop	Class II	Double Insulated	>19.99MΩ	<.010mA	Υ		
0201	Cable	Cable	0.04Ω	0.31Ω		GOOD	PASS	Riso Fail Tested at 500v 13A fuse
0202	Cable	Cable	0.05Ω	0.30Ω		GOOD	PASS	Riso Fail Tested at 500v 13A fuse
0203	Cable	Cable	0.04Ω	0.31Ω		GOOD	PASS	Riso Fail Tested at 500v 13A fuse
0204	Cable	Cable	0.05Ω	0.31Ω		GOOD	PASS	Riso Fail Tested at 500v 13A fuse
0205	Cable	Cable	0.05Ω	0.31Ω		GOOD	PASS	Riso Fail Tested at 500v 13A fuse
0206	Cable	Cable	0.05Ω	0.30Ω		GOOD	PASS	Riso Fail Tested at 500v 13A fuse
0207	Cable	Cable	0.05Ω	0.30Ω		GOOD	PASS	Riso Fail Tested at 500v 13A fuse
0208	Microphones	Class II	Double Insulated	0.30Ω	<.010mA	COOD	PASS	Trise i all rested at 5000 To/Trise
		Olass II			1.0 TOTIA	GOOD	PASS	13A Fuse
0209	Cables	Class 1	0.03Ω 0.04Ω	>19.99MΩ >19.99MΩ	0.13mA	Y	PASS	10/11/10/10
0210	Light	Class 1				<u> </u>		
0211	Light	Class 1	0.06Ω	>19.99MΩ	0.13mA	Y	PASS	404 5
0212	Cable	Cable	0.02Ω	>19.99MΩ		GOOD	PASS	10A Fuse
0213	Cable	Cable	0.03Ω	>19.99MΩ		GOOD	PASS	10A Fuse
0214	PSU	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0215	PSU	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0216	Cable	Cable	0.03Ω	>19.99MΩ		GOOD	PASS	3A Fuse
0217	Lights	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0218	Lights	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
0219	Lights	Class II	Double Insulated	>19.99MΩ	<.010mA	Y	PASS	
				·				